2007 MERCEDES-BENZ CL 600 Coupe | 12 Cylinders | Gas WDDEJ76X57A003115

**Accident/Damage Records Found** 

No U.S. History Found

**Country of Assembly: Germany** Last Reported Odometer: 187,500 KM 1

No Open Recalls Found

Last Registered In: **22** Service Records Found **Ontario (Normal)** 



Report Date: August 9, 2021 | 08:52 PM EST

**Report Status:** Complete


Not Actively Declared Stolen

**AMOUNT** 

\$1,083.00

\$1,957.00

FR



Questions? We're here to help. 1.866.835.8612 | Customer Support Portal No Import Record Found

This vehicle history report is based on information that was reported and available to CARFAX Canada as of

August 9, 2021 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# Accident/Damage •

### **INCIDENT DATE DETAILS** 2011 May 6 Ontario, Canada Claim: Damage

Ontario, Canada

Claim: Damage

SOURCE

**NV Euro Motor Works** 

NV Euro Motor Works

NV Euro Motor Works

NV Euro Motor Works

**NV Euro Motor Works** 

**NV Euro Motor Works** 

NV Euro Motor Works

NV Euro Motor Works

**NV Euro Motor Works** 

NV Euro Motor Works

**NV Euro Motor Works** 

**NV Euro Motor Works** 

**NV Euro Motor Works** 

OK Tire

Unionville, Ontario, Canada

Pickering, Ontario, Canada

Unionville, Ontario, Canada

**Vehicle History Report** 

2012 Jul 12

Registration • This vehicle has been registered in the province of Ontario in Canada with Normal branding. We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

**DETAILS** 

Vehicle serviced

Vehicle serviced

Vehicle serviced

Vehicle serviced

Vehicle serviced

Vehicle serviced

**Vehicle serviced** 

Vehicle serviced

Vehicle serviced

Vehicle serviced

**Vehicle serviced** 

Vehicle serviced

**Vehicle serviced** 

Vehicle serviced

**Vehicle serviced** 

**Vehicle serviced** 

Vehicle serviced

Vehicle serviced

Vehicle serviced

Vehicle serviced

Vehicle serviced

**Vehicle serviced** 

**RECORD TYPE** 

Canadian Renewal

Canadian Renewal

Canadian Renewal

Canadian Renewal

Odometer reading

Canadian Renewal

Canadian Renewal

Canadian Renewal

Previous use

Previous use

Damage

Damage

Canadian Renewal

Canadian Renewal

Previous use

Service Record

Canadian Renewal

Previous use

Service Record

Canadian Renewal

Previous use

Service Record

Service Record

Service Record

Service Record

Canadian Renewal

Previous use

Service Record

Odometer reading

Canadian Renewal

Canadian Renewal

Previous use

Service Record

Canadian Renewal

Canadian Renewal

Canadian Renewal

Previous use

Previous use

**DETAILS** 

First Owner Reported

Registration Issued or Renewed

Registration Issued or Renewed

Registration Issued or Renewed

Commercial

New Owner Reported

Personal

Personal

Personal

Vehicle serviced

Personal

Vehicle serviced

Personal

Vehicle serviced

Vehicle serviced

Vehicle serviced

Vehicle serviced

Registration Issued or Renewed

Registration Issued or Renewed

New Owner Reported

Registration Issued or Renewed

Registration Issued or Renewed

Registration Issued or Renewed

Tire repaired

Air filter replaced

Fluids checked

Oil and filter changed

Oil and filter changed

Alignment performed Front strut(s) replaced

• Rear differential replaced

Oil and filter changed

Spark plug(s) replaced

Oil and filter changed

Lower control arm(s) replaced

Alignment performed Control arm(s) replaced

Cabin air filter replaced/cleaned

Emissions inspection performed

Crankshaft position sensor replaced

Air filter replaced

Wheel(s) replaced

Drive belt(s) replaced

Battery replaced

Oil and filter changed

Battery/charging system checked

Recommended maintenance performed

Power steering hose(s)/line(s) replaced

Recommended maintenance performed

Maintenance inspection completed

Cooling system checked Antifreeze/coolant checked

Spark plug(s) replaced

Oil and filter changed

Air filter replaced Brakes checked

Brakes checked

Brake pads replaced

Switch replaced/repaired

Power steering pump replaced

Power steering checked

Vehicle washed/detailed

Brake pads replaced

Steering/suspension checked

Brake fluid flushed/changed

Oil and filter changed

Headlight bulb(s) replaced

Air filter replaced Lights checked Fluids checked Brakes checked

Four wheel alignment performed

Brakes checked

Radiator/condenser fan motor replaced

Brakes checked

Rear brake pads replaced

Brake rotor(s) resurfaced

Oil pan gasket replaced

Cabin air filter replaced/cleaned

Transmission filter replaced

Maintenance reminder reset

Brake pad sensor(s) replaced

Front brake rotor(s) replaced

## DATE ~ **ODOMETER** 2013 Dec 16 114,835 KM

## 2014 May 2 118,755 KM

2014 Jul 31 122,560 KM

128,413 KM

128,833 KM

130,420 KM

133,513 KM

145,514 KM

145,979 KM

148,068 KM

153,229 KM

157,518 KM

164,448 KM

180,213 KM

182,141 KM

Open Recalls

This vehicle is not actively declared stolen.

Detailed History •

**ODOMETER** 

14,532 KM

SOURCE

Motor Vehicle Dept.

Independent Source

Motor Vehicle Dept.

Ontario, Canada

Ontario, Canada

Motor Vehicle Dept.

Ontario, Canada

Ontario, Canada

Motor Vehicle Dept.

Motor Vehicle Dept.

**NV Euro Motor Works** 

**NV Euro Motor Works** 

NV Euro Motor Works

**NV Euro Motor Works** 

NV Euro Motor Works

NV Euro Motor Works

**NV Euro Motor Works** 

Motor Vehicle Dept.

Motor Vehicle Dept.

NV Euro Motor Works

**NV Euro Motor Works** 

**NV Euro Motor Works** 

**NV Euro Motor Works** 

Motor Vehicle Dept.

Motor Vehicle Dept.

**NV Euro Motor Works** 

**NV Euro Motor Works** 

**NV Euro Motor Works** 

**NV Euro Motor Works** 

Motor Vehicle Dept.

Motor Vehicle Dept.

**NV Euro Motor Works** 

Independent Source

Motor Vehicle Dept.

Ontario, Canada

Questions? We're here to help.

1.866.835.8612 | Customer Support Portal | FAQ & Glossary

100 Kellogg Ln Suite 301, London ON N5W 0B4

Ontario, Canada

Ontario, Canada

Ontario, Canada

Pickering, Ontario, Canada

Ontario, Canada

**OK Tire** 

Ontario, Canada

Ontario, Canada

Toronto, Ontario, Canada

Unionville, Ontario, Canada

Ontario, Canada

Ontario, Canada

Unionville, Ontario, Canada

Unionville, Ontario, Canada

Unionville, Ontario, Canada

Unionville, Ontario, Canada

Ontario, Canada

Ontario, Canada

Unionville, Ontario, Canada

Ontario, Canada

Ontario, Canada

Unionville, Ontario, Canada

Newmarket, Ontario, Canada

Ontario, Canada

Ontario, Canada

Ontario, Canada

Ontario, Canada

Ontario, Canada

Benz's website.

2014 Oct 30

2015 Oct 15

2019 Feb 20 2019 Aug 2 No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact MERCEDES-BENZ or visit Mercedes

DATE \ 2007 Jan 9 2007 Jan 9

2007 May 1

2007 Aug 1

2007 Aug 1

2008 Jul 1

2010 Nov 1

2010 Nov 1

2011 May 6

2011 Jun 27

2012 Jul 12

2012 Nov 1

2012 Nov 1

2013 Dec 16

2014 May 2

2014 Jul 31

2014 Aug 11

2014 Aug 26

2014 Oct 6

2014 Oct 30

2014 Nov 1

2014 Nov 1

114,835 KM

118,755 KM

122,560 KM

128,413 KM

128,833 KM

2015 Jun 30 2015 Oct 15 2015 Oct 30 2015 Nov 17 2016 Apr 22 153,229 KM

2016 Oct 13

2016 Nov 1

2016 Nov 1

2017 May 5

2017 May 25

2018 Jan 27

2018 Oct 12

2018 Nov 1

2018 Nov 1

2019 Feb 20

2019 Mar 23

2019 Jun 20

2019 Jun 20

2019 Jun 20

2019 Aug 2

2020 Jun 1

2020 Jun 1

2020 Jun 1

2020 Dec 15

CAR FOX

148,068 KM

133,513 KM 145,514 KM 145,979 KM

2014 Dec 15 130,420 KM

157,518 KM

164,448 KM

180,213 KM

182,141 KM

187,500 KM

Registration Issued or Renewed Personal Vehicle serviced New Owner Reported Registration Issued or Renewed Personal Vehicle serviced New Owner Reported

Registration Issued or Renewed

Personal

New Owner Reported

